

ABSTRACT

The invention teaches a multi-step method for shutting down the dry-etch process. The ICP rf power is reduced between each of these consecutive power-down steps of the dry-etch process, the complete power-down sequence consists of six steps. These six steps are executed in sequence and without interruption and form the totality of the dry-etch chamber power-down procedure.